03500.015727.1 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TAKEO TSUKAMOTO	: Examiner: Anne M. Hine
Appln. No.: 10/799,859	: Art Unit: 2879
Filed: March 15, 2004	: Conf. No.: 7003
For: ELECTRON-EMITTING DEVICE.	:
ELECTRON-EMITTING APPARATUS, IMAGE DISPLAY APPARATUS, AND	:
LIGHT-EMITTING APPARATUS	;
U.S. Patent No.: 7,186,160 B2	;
Issued: March 6, 2007) : February 13, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of

Correction form, in duplicate, is enclosed.

The amount of \$100.00 to cover the statutory fee for such Certificate of

Correction is being paid concurrently; please charge any deficiency in the fee, and credit

any overpayment, to Deposit Account 50-3939.

Patentees' undersigned attorney may be reached in our New York office by

telephone at (212) 218-2100. All correspondence should continue to be directed to our

address given below.

Respectfully submitted,

/Frank A. DeLucia/

Frank A. DeLucia Attorney for Patentees

Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

Facsimile: (212) 218-2200

FCHS_WS 1950012v1

- 2 -

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : US 7.186.160 B2 : March 6, 2007 DATED

INVENTOR(S) : TAKEO TSUKAMOTO

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE (56) REFERENCES CITED:

U.S. Patent Documents.

"5,382,867 A 1/1995 Yuji et al." should read -- "5,382,867 A 1/1995 Maruo et al.--.

"2002/0009637 A1 1/2002 Murakamiet al." should read --2002/0009637 A1 1/2002 Murakami et al.--; and

Foreign Patent Documents.

"EP 0 989 084 A2 3/2000" should read -- EP 0 986 084 A2 3/2000--, "JP WO 89/07163 8/1989" should read -- WO WO 89/07163 8/1989--: and

Other Publications.

T. Guo et al.: "Single- Walled" should read -- Single-Walled--. A.C. Dillon et al.,: "Single- Walled" should read -- Single-Walled--. Delete "C.A. Spindt et al., ...pp. 5248-5263." second occurrence, G. Dittmer,: "Thin Film"," should read -- Thin Films", --. A.M. Rao et al ..: Delete "of", and A.M. Rao et al ..: "Letter." should read -- Letters --

COLUMN 5:

Line 29, "so-that" should read --so that --.

COLUMN 6:

Line 50, "AS" should read -- As --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. US 7.186.160 B2



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

US 7,186,160 B2 PATENT NO. March 6, 2007

TAKEO TSUKAMOTO INVENTOR(S) :

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

DATED

Line 18, "10 nm" should read -- 10 nm and --.

COLUMN 10:

Line 44, "improved-reliability." should read --improved reliability.--; and Line 52, "No," should read --Ni, --.

COLUMN 11:

Line 7, "case," should read --cases, --: Line 20, "a" first occurrence should read --an--; and Line 41, "field)" should read --field))--.

COLUMN 12:

Line 59, "envelop" should read --envelope--; and Line 63, "envelop" should read --envelope--.

COLUMN 13:

Line 2, "be-directly" should read --be directly--: Line 3, "envelop" should read --envelope--; Line 7, "envelop" should read --envelope--; and Line 9, "will-be" should read --will be--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. __US 7,186,160 B2



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 7,186,160 B2

DATED : March 6, 2007

INVENTOR(S) : TAKEO TSUKAMOTO

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 50, "was" should read --were--.

COLUMN 15:

Line 56, "film-having" should read --film having--; and

Line 63, "arrangement-enabled" should read -- arrangement enabled --.

COLUMN 16:

Line 9, "fabricated" should read --fabricated according to--; and Line 54, "in" should read --m--.

COLUMN 17:

Line 23, "envelop" should read --envelope--;

Line 30, "envelop" should read --envelope--;

Line 34, "envelop" should read --envelope--; Line 41, "on" should read --on the--; and

Line 46, "voltage" should read --voltages--.

COLUMN 18:

Line 37, "thresh old" should read --threshold --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) FCHS WS 1950012v1 PATENT NO. US 7,186,160 B2



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 7,186,160 B2

INVENTOR(\$) : TAKEO TSUKAMOTO

March 6, 2007

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19:

DATED

Line 3, "are-added" should read -- are added --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) FCHS WS 1950012v1 PATENT NO. US 7,186,160 B2

